



SITE INSPECTION REPORT

Page:

2 of 3



Photo showing installation of reinfocement.



Waterstop located in side wall



SITE INSPECTION REPORT

Page:

3 of 3



Corner reinforcement